

[illegible]

	06920	F1	Q2	289036	FEE	PERM	61050	ADMIN GEN PURP	8186	SF	Toxic substance survey (2016) identified asbestos-containing materials (i.e. roof sealant, and caulking) and no lead identified in paint; no condition of building material to access risk or need to review ISR inspection report	RC007693J Remove black mastic material and retile breakroom floor	
12	06922	nr	nr	289038	FEE	TEMP	45210	OPEN STORAGE AREA, INSTALLATION	2222	SY	No record in the ACM/LBP database		
13	06924	nr	nr	289040	FEE	TEMP	21870	MNT STORAGE DOL	10340	SF	No toxic substance (asbestos and lead paint) survey for this facility; unknown condition but will have to make generalities based on year of construction or ISR inspection report	Work order FE000983J: Request to demolish six abandoned PRIV bldgs. in 6900 area	Missing Bldg. 6923: No toxic substance (asbestos and lead paint) survey for this facility; unknown condition but will have to make generalities based on year of construction or ISR inspection report
14	06928	nr	nr	289043	FEE	TEMP	61050	ADMIN GEN PURP	1680	SF	No record in the ACM/LBP database		
15	06949	nr	nr	289045	PRIV	TEMP	61050	ADMIN GEN PURP	1747	SF	Portable trailer; toxic substance survey (2014) for asbestos and lead, none were identified; need to re-evaluate to determine if all suspect materials were tested to determine risk from presence and condition	RC000892J Remove Bldg. 6949 from Real Property/Master Planning	Missing Bldg. 6948: No toxic substance (asbestos and lead paint) survey for this facility; unknown condition but will have to make generalities based on year of construction or ISR inspection report
16	06950	nr	nr	289046	PRIV	TEMP	44220	STORAGE GP INST	1740	SF	No toxic substance (asbestos and lead paint) survey for this facility; unknown condition but will have to make generalities based on year of construction or ISR inspection report	Work order FE000973J: Request to demolish six abandoned PRIV Bldgs.	
17	06952	F1	Q1	289048	FEE	PERM	21885	MAINTENANCE SHOP, GENERAL PURPOSE	11528	SF	No toxic substance (asbestos and lead paint) survey for this facility; unknown condition but will have to make generalities based on year of construction or ISR inspection report		Missing Bldg. 6953: No toxic substance (asbestos and lead paint) survey for this facility; unknown condition but will have to make generalities based on year of construction or ISR inspection report
18	06954	F2	Q2	280713	FEE	PERM	21415	COMP ITEM REP	2002	SF	No toxic substance (asbestos and lead paint) survey for this facility; unknown condition of remaining suspect building materials; pipe (insulation or pipe) was abated (1988) but records do not identify material abated (i.e. insulation or pipe) but will have to make generalities based on year of construction or ISR inspection report	Work order FE000847J: Request for demolition of Bldg.	

06956	F1	Q2	289050	FEE	PERM	21415	COMP ITEM REP	7568	SF	No toxic substance (asbestos and lead paint) survey for this facility; unknown condition of remaining suspect building materials; pipe (insulation or pipe) was abated (1988) but records do not identify material abated (i.e. insulation or pipe) but will have to make generalities based on year of construction or ISR inspection report
20										
21 06957	F3	Q3	289051	FEE	SEMI	81160	STANDBY GENERATOR	240	KW	Not applicable
22 06958	nr	nr	289052	FEE	SEMI	12483	LP GAS STR ABV	800	GA	Not applicable
23 06959	nr	nr	289053	FEE	SEMI	12483	LP GAS STR ABV	1000	GA	Not applicable
06960	nr	nr	289054	FEE	TEMP	17132	GEN REP INST	384	SF	Not applicable
24										
25 06962	nr	nr	289055	FEE	SEMI	12483	LP GAS STR ABV	1000	GA	Not applicable
26 06963	nr	nr	289056	FEE	SEMI	12483	LP GAS STR ABV	1000	GA	Not applicable

FE006292J Environmental assessment of Bldg. 6960